


# Gerber Collision & Glass

Tacoma, Washington



EAST ELEVATION  
GERBER COLLISION



Merritt Arch worked with the client and contractor on an accelerated schedule....

Merritt Arch worked with the client and contractor on an accelerated time schedule to remodel a newly leased building. The client needed the remodel done on this quick schedule because of their lease agreement with their client. The project met all of the construction deadlines through substantial completion.